

Home report



thorntons-property.co.uk

Thorntons is a trading name of Thorntons Law LLP

west we not stold

Property address

WHITE GABLES

WE KINGSWAY

DUN DEE

DDL 9BP

Seller(s)

MR COHN C PAIMAN N MS S TENMAN

Completion date of property
questionnaire

Illo MARCH 2020

torrespond between M. Jehnny sussissimus (China) to each sign of find)) waste were ensured between the first in grant of aug/ newable architicality) or inferenced inforwalt the character or Specifical on the contract of an experience of acceptance of ad Pacil HARRIST CHARLES as your property is Listed Societies, or expressions stilled own talbaga to exhad up havorage tora incolnectate problems a statem? gaY-Privinger projectate se fearresterm THE PARTY AND TH CONT. interests will an improve as anothers and female residual. 264 These shart to shallow must be seen as that in the said while will live to

Note for sellers

- Please complete this form carefully. It is important that your answers are correct.
- The information in your answers will help ensure that the sale of your house goes smoothly. Please answer each question with as much detailed information as you can.
- If anything changes after you fill in this questionnaire; but before the date of entry for the sale of your house, tell your solicitor or estate agent immediately.

Information to be given to prospective buyer(s)

1	Length of ownership	7.	
MINISTER	How long have you owned the property? 12. YEAR	s	
2.	Counciltax		2//
	Which Council Tax band is your property in? (Please tick) A B C D E F G H	define the of	AND THE
3.	Parking	E WITCHES	P.VEL
7072707	What are the arrangements for parking at your property? (Please tick all that apply)		
	Garage		
	Allocated parking space		
	Driveway		
81.4	Shared parking		
1	Onstreet		192
1	Resident permit		
	Metered parking		
	Other (please specify):		
4.	Conservationarea		
	Is your property in a designated Conservation Area (that is an area of special architectural or historical interest, the character or appearance of which it is desirable to preserve or enhance)?	Yes No Don't know	口口 ù
5.	Liste d buildings		
	Is your property a Listed Building, or contained within one (that is a building recognised and approved as being of special architectural or historical interest)?	Yes No	
6.	Albertaions/ackillions/extensions	MANUFAN.	
a	(I) During your time in the property, have you carried out any structural alterations, additions or extensions (for example, provision of an extra bath/shower room, toilet, or bedroom)?	Yes No	

1387	If you have answered yes, please describe below the changes which you have made:	(a) the part in equipment of	
	A DECEMBER OF THE PARTY OF THE	de stanto attie	
光	(ii) Did you obtain planning permission, building warrant, completion certificate and other consents for this work? If you have answered yes, the relevant documents will be needed by the purchaser and you should give them to your solicitoras soon as possible for checking. If you do not have the documents yourself, please note below who has these documents and your solicitor or estate agent will arrange to obtain them:	Yas No	
h 198	Have you had replacement Windows, doors, patio doors or double glazing installed in your property? If you have answered yes, please answer the three questions below:	Yes No	S
O	(i) Were the replacements the same shape and type as the ones you replaced?	Yes No	F
1	(ii) Did this work involve any changes to the window or door openings?	Yes No	
	(iii) Please describe the changes made to the windows doors of approximate dates when the work was completed): REPLACEMENT DOUBLE ENAZING IN FRONT + BACK OF FRENCH DOORS REPLACED OUD SUIDING PATIO DOOR IN Please give any guarantees which you received for this work to estate agent. NONE.	HOUSE, NEW NEW BACK DO	O.C.
7.	Central heating		MER
a.	is there a central heating system in your property? (Note: a partial central heating system is one which does not heat all the main rooms of the property— the main living room, the bedroom(s), the half and the bathroom).	Yes No Partial	
	if you have answered yes or partial — what kind of central heating is there? (Examples: gas-fired, solid fuel, electric storage heating, gas warm air).	gas- reed	
Ayr	If you have answered yes, please answer the three questions below:		
	i) When was your central heating system or partial central heating system installed?	BOILER REPU	N CED

	(ii) Do you have a maintenance contract for the central heating system? If you have answered yes, please give details of the company with which you have a maintenance contract:	Yes No	S
	(iii) When was your maintenance agreement last renewed? (Please provide the month and year).		
8.	Energy Performance Certificate	O MINISTER	
	Does your property have an Energy Performance Certificate which is less than 10 years old?	Yes No	
9.	Issues that may have affected your property		A LOUIS
2.	Has there been any storm, flood, fire or other structural damage to your property while you have owned it?	Yes No	
	If you have answered yes, is the demage the subject of eny outstanding insurance claim?	Yes No	
b.	Are you aware of the existence of asbestos in your property? If you have answered yes, please give details:	Yes No	

10.	Services	mally assisted in the te-	of him of Mulchel	Dograma	- 5
a. Pto suppli	ease tick which services a ler:	re connected to your p	roperty and give d	etails of the	
Servi	içes	Connected	Supplier	8. 21731-108.VI	
Gas	or liquid petroleum gas	YES	Scarns	H 643	
	er mains or private r supply	YES	SEOTTISH	WATER.	-4
Elect	tricity	YES	SOTTISM	GAS .	49
Main	s drainage	YES	Scottes	WATEL	11.35
Telep	phone	YES	VIEGIN	MEDIA	The second
Cabl	e TV or satellite	YES	Viechil	MEDIA	
Broa	ndband	YES	VIRGIN	MEDIA.	
· ×	Mio				
b.	is there a septic tank sy if you have answered yo below:			Yes No	
V	(i) Do you have appropriyour septic tank?	ate consents for the d	ischarge from	Yes No Don't know	
	(ii) Do you have a maint If you have answered you with which you have a r	please give details	of the company	Yes No	
11.	Responsibilities for sha	red or common areas			100
a.	Are you aware of any res anything used jointly, su road, boundary, or garde	ch as the repair of a sha	red drive, private	Yes No Don't know	
2					
b	is there a responsibility the roof, common stairw	o contribute to repair are	nd maintenance of	Yes No Don't know	
福	If you have answered yes			DOIT MIOW	
C.	Has there been any majo roof during the time you			Yes No	

		er grystad	-
d.	Do you have the right to walk over any of your neighbours' property— for example to put out your rubbish bin or to maintain your boundaries?	Yes No	
1	If you have answered yes, please give details:	4.93	Saro
	As far as you are aware, do any of your neighbours have the right	Yes	D
в.	to walk over your property, for example to put out their rubbish bin or to maintain their boundaries?	No	V
	if you have answered yes, please give details:	Salding.	and the same
	As far as your re aware, is there a public right of way across any part of your property? (public right of way is a way over which the public has a right to pass, whether or not the land is	Yes No special series	
-ti	privately-owned.)	6/10/8	Carle P
	If you have answered yes, please give details:	estimate of Vi	obstate [
12.	Charges associated with your property	The sale	MANA
a	is there a factor or property manager for your property?	Yes No	
100	If you have answered yes, please provide the name and address, and give details of any deposit held and approximate charges:	The stance e cap If you invo a maked	4
b.	is there a common buildings insurance policy?	Yes	口
1	If you have answered yes, is the Cost of the insurance included in your monthly/annual factor's charges?	No Don't know	
C.	Please give details of any other charges you have to pay one regula upkeep of common areas or repair works, for example to a resident maintenance or stair fund.		и
13,	Specialist works		MARIE
а	As far as you are aware, has treatment of dry rot, wet rot, damp or any other specialist work ever been carried out to your property?	Yes No	
Į	If you have answered yes, please say what the repairs were for, whether you carried out the repairs (and when) or if they were done before you bought the property.	pody A site (fille)	
	As far as you are aware, has any preventative work for dry rot, wet tot, or damp ever been carried out to your property?	Yes No	
b.	If you have answered yes, please give details:		
Na.	way of arts to transpose to invocabalizer to stages mison with a parties of the property of the parties of the		

671	If you have answered yes to 13(a) or (b), guarantees relating to this work?	do you hav	e any	O'VIO VIGENE	Yes No	
C. ndi	If you have answered yes, these guarant purchaser and should be given to your a possible for checking. If you do not have your solicitor or estate agent will arrang You will also need to provide a description. This may be shown in the original extensions.	collectoras them you for them on of the w	soon as rself to be obt	and alried.		
	Guarantees are held by:					
14.	Guarantees			Maria dia		o (activist)
а.	Are there any guarantees or warranties	for all y of t	he follow	ring:	As to At market	
	SUPPLIES HE SHOULD BE SOUTH THE SECTOR	No	Yes	Don't know	With title deeds	Lost
(1)	Electrical work	V				
(ii)	Roofing	V.	D-4 E 27	ALC: NO	A PARTY	
(iii)	Central heating			V		
(iv)	National House Building Council (NHBC)	Ø				
(v)	Damp course	Q		14 m/s	10//	
(vi)	Any otherwork or installations? (for example, cavity wall insulation, underpinning, indemnity policy)					
b	If you have answered 'yes' or 'with title installations to which the guarantee(s) r	deeds', ple elate(s):	ase give	details of	the work or	
c	Are there any outstanding claims under listed above? If you have answered yes, please give descriptions.	No. (6)	guarante	8 5	Yes No	
15.	Boundaries					71 () X (8)
	So far as you are aware, has any bounds moved in the last 10 years? If you have answered yes, please give d		property	been	Yes No Don't know	
16.	Notices that affect your property					Land I
	In the past three years have you ever	received a	notice:	MI		1200
а.	advising that the owner of a neighbour planning application?	ring prope	rty has r	nade a	Yes No	

b	that alects y	our property	al South Office	Hay t	No No	V
G.	3 0 7 3 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	you to do any ts to your pro		, repairs or	Yes No	
	solicitor or e	nswered yes state agent, in of the purcha	ncluding any r	above, please give the notices which arrive at roperty.	notices to your any time before	the o
					HIL DESITE AVE	
Declar	etion by the s	eller(s)/or other	er authorised	body or person(s)	exciteres 20.	
	onfirm that the		n this form is	true and correct to the	e best of Myour	
					Slacknow w.	05-
Signat	ure(s):				gnitical	(03
	FULL	[6]			Central tecaung	919
d		n l n	100	,	Status Houses (HERRS)	(pi)
Date:	16/3	12020	18	14/8/2020	Овени фолтин	(9)
			(5)	material fractification	Any other work of the assemble, car underplacing, in	(IN)
	ad Aless and a	n idlatoh isstg	desert, inserte store(a):	(a)out-mouse and cold	Name of Street Street St.	
4	897 688	(UC2081)	mb was a Atal	refered terrifical gradiential	Na Deep my on Fried Stare?	9
			lattida	o erie sonis des laste	serve averd fram 18	
					Finishmed	
13	ROY	прод ублафі	on, they're per	Francis you shill assess it is carry it?	ent stoy as takes aut on til beleast	
U.S.C.	Dan't kappe			in over preside their g	Wyers Insert season	
				Abbidose mon pa	Notices that area	,81
		9,04	kin a bevieur	VALUE FRANCE PROCESSOR I	serviti tang past pi	
	Yas			of a light of the sections		

Energy Performance Certificate (EPC)

Dwellings

Scotland

62 KINGSWAY, DUNDEE, DD4 9BP

Dwelling type: Detached bungalow
Date of assessment: 19 March 2020
Date of certificate: 19 March 2020

Total floor area: 120 m²

Primary Energy Indicator: 241 kWh/m²/year

Reference number: 9810-1012-9207-9540-0204 **Type of assessment:** RdSAP, existing dwelling

Approved Organisation: Elmhurst

Main heating and fuel: Boiler and radiators, mains


gas

You can use this document to:

- Compare current ratings of properties to see which are more energy efficient and environmentally friendly
- Find out how to save energy and money and also reduce CO₂ emissions by improving your home

Estimated energy costs for your home for 3 years*	£3,309	See your recommendations
Over 3 years you could save*	£789	report for more information

* based upon the cost of energy for heating, hot water, lighting and ventilation, calculated using standard assumptions




Energy Efficiency Rating

This graph shows the current efficiency of your home, taking into account both energy efficiency and fuel costs. The higher this rating, the lower your fuel bills are likely to be.

Your current rating is **band D (67)**. The average rating for EPCs in Scotland is **band D (61)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.



Environmental Impact (CO₂) Rating

This graph shows the effect of your home on the environment in terms of carbon dioxide (CO_2) emissions. The higher the rating, the less impact it has on the environment.

Your current rating is **band D (61)**. The average rating for EPCs in Scotland is **band D (59)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

Top actions you can take to save money and make your home more efficient

Recommended measures	Indicative cost	Typical savings over 3 years
1 Cavity wall insulation	£500 - £1,500	£237.00
2 Floor insulation (suspended floor)	£800 - £1,200	£339.00
3 Low energy lighting	£40	£126.00

A full list of recommended improvement measures for your home, together with more information on potential cost and savings and advice to help you carry out improvements can be found in your recommendations report.

To find out more about the recommended measures and other actions you could take today to stop wasting energy and money, visit greenerscotland.org or contact Home Energy Scotland on 0808 808 2282.

THIS PAGE IS THE ENERGY PERFORMANCE CERTIFICATE WHICH MUST BE AFFIXED TO THE DWELLING AND NOT BE REMOVED UNLESS IT IS REPLACED WITH AN UPDATED CERTIFICATE

Summary of the energy performance related features of this home

This table sets out the results of the survey which lists the current energy-related features of this home. Each element is assessed by the national calculation methodology; 1 star = very poor (least efficient), 2 stars = poor, 3 stars = average, 4 stars = good and 5 stars = very good (most efficient). The assessment does not take into consideration the condition of an element and how well it is working. 'Assumed' means that the insulation could not be inspected and an assumption has been made in the methodology, based on age and type of construction.

Element	Description	Energy Efficiency	Environmental
Walls	Cavity wall, as built, no insulation (assumed)	***	***
Roof	Pitched, insulated at rafters Roof room(s), ceiling insulated	**** ****	**** ****
Floor	Suspended, no insulation (assumed)	_	<u>—</u>
Windows	Fully double glazed	****	***☆
Main heating	Boiler and radiators, mains gas	****	***☆
Main heating controls	Programmer, room thermostat and TRVs	****	***☆
Secondary heating	None	_	<u>—</u>
Hot water	From main system	****	★★★ ☆
Lighting	Low energy lighting in 43% of fixed outlets	***	***

The energy efficiency rating of your home

Your Energy Efficiency Rating is calculated using the standard UK methodology, RdSAP. This calculates energy used for heating, hot water, lighting and ventilation and then applies fuel costs to that energy use to give an overall rating for your home. The rating is given on a scale of 1 to 100. Other than the cost of fuel for electrical appliances and for cooking, a building with a rating of 100 would cost almost nothing to run.

As we all use our homes in different ways, the energy rating is calculated using standard occupancy assumptions which may be different from the way you use it. The rating also uses national weather information to allow comparison between buildings in different parts of Scotland. However, to make information more relevant to your home, local weather data is used to calculate your energy use, CO₂ emissions, running costs and the savings possible from making improvements.

The impact of your home on the environment

One of the biggest contributors to global warming is carbon dioxide. The energy we use for heating, lighting and power in our homes produces over a quarter of the UK's carbon dioxide emissions. Different fuels produce different amounts of carbon dioxide for every kilowatt hour (kWh) of energy used. The Environmental Impact Rating of your home is calculated by applying these 'carbon factors' for the fuels you use to your overall energy use.

The calculated emissions for your home are 42 kg CO₂/m²/yr.

The average Scottish household produces about 6 tonnes of carbon dioxide every year. Based on this assessment, heating and lighting this home currently produces approximately 5.1 tonnes of carbon dioxide every year. Adopting recommendations in this report can reduce emissions and protect the environment. If you were to install all of these recommendations this could reduce emissions by 2.2 tonnes per year. You could reduce emissions even more by switching to renewable energy sources.

Estimated energy costs for this home

	Current energy costs	Potential energy costs	Potential future savings
Heating	£2,631 over 3 years	£2,073 over 3 years	
Hot water	£282 over 3 years	£195 over 3 years	You could
Lighting	£396 over 3 years	£252 over 3 years	save £789
Total	s £3,309	£2,520	over 3 years

These figures show how much the average household would spend in this property for heating, lighting and hot water. This excludes energy use for running appliances such as TVs, computers and cookers, and the benefits of any electricity generated by this home (for example, from photovoltaic panels). The potential savings in energy costs show the effect of undertaking all of the recommended measures listed below.

Recommendations for improvement

The measures below will improve the energy and environmental performance of this dwelling. The performance ratings after improvements listed below are cumulative; that is, they assume the improvements have been installed in the order that they appear in the table. Further information about the recommended measures and other simple actions to take today to save money is available from the Home Energy Scotland hotline which can be contacted on 0808 808 2282. Before carrying out work, make sure that the appropriate permissions are obtained, where necessary. This may include permission from a landlord (if you are a tenant) or the need to get a Building Warrant for certain types of work.


Recommended measures		Indicative cost	Typical saving	Rating after improvement		
		indicative cost	per year	Energy	Environment	
1	Cavity wall insulation	£500 - £1,500	£79	C 69	D 65	
2	Floor insulation (suspended floor)	£800 - £1,200	£113	C 73	C 69	
3	Low energy lighting for all fixed outlets	£40	£42	C 74	C 70	
4	Solar water heating	£4,000 - £6,000	£29	C 75	C 72	
5	Solar photovoltaic panels, 2.5 kWp	£3,500 - £5,500	£306	B 83	C 79	

Alternative measures

There are alternative improvement measures which you could also consider for your home. It would be advisable to seek further advice and illustration of the benefits and costs of such measures.

External insulation with cavity wall insulation

Choosing the right improvement package





About the recommended measures to improve your home's performance rating

This section offers additional information and advice on the recommended improvement measures for your home

1 Cavity wall insulation

Cavity wall insulation, to fill the gap between the inner and outer layers of external walls with an insulating material, reduces heat loss; this will improve levels of comfort, reduce energy use and lower fuel bills. The insulation material is pumped into the gap through small holes that are drilled into the outer walls, and the holes are made good afterwards. As specialist machinery is used to fill the cavity, a professional installation company should carry out this work, and they should carry out a thorough survey before commencing work to ensure that this type of insulation is suitable for this home and its exposure. They should also provide a guarantee for the work and handle any building standards issues. Further information about cavity wall insulation and details of local installers can be obtained from the National Insulation Association (www.nationalinsulationassociation.org.uk).

2 Floor insulation (suspended floor)

Insulation of a floor will significantly reduce heat loss; this will improve levels of comfort, reduce energy use and lower fuel bills. Suspended floors can often be insulated from below but must have adequate ventilation to prevent dampness; seek advice about this if unsure. Further information about floor insulation is available from many sources including www.energysavingtrust.org.uk/scotland/Insulation/Floor-insulation. Building regulations generally apply to this work so it is best to check with your local authority building standards department.

3 Low energy lighting

Replacement of traditional light bulbs with energy saving bulbs will reduce lighting costs over the lifetime of the bulb, and they last many times longer than ordinary light bulbs. Low energy lamps and fittings are now commonplace and readily available. Information on energy efficiency lighting can be found from a wide range of organisations, including the Energy Saving Trust (http://www.energysavingtrust.org.uk/home-energy-efficiency/lighting).

4 Solar water heating

A solar water heating panel, usually fixed to the roof, uses the sun to pre-heat the hot water supply. This can significantly reduce the demand on the heating system to provide hot water and hence save fuel and money. Planning permission might be required, building regulations generally apply to this work and a building warrant may be required, so it is best to check these with your local authority. You could be eligible for Renewable Heat Incentive payments which could appreciably increase the savings beyond those shown on your EPC, provided that both the product and the installer are certified by the Microgeneration Certification Scheme (or equivalent). Details of local MCS installers are available at www.microgenerationcertification.org.

5 Solar photovoltaic (PV) panels

A solar PV system is one which converts light directly into electricity via panels placed on the roof with no waste and no emissions. This electricity is used throughout the home in the same way as the electricity purchased from an energy supplier. Planning permission might be required, building regulations generally apply to this work and a building warrant may be required, so it is best to check with your local authority. The assessment does not include the effect of any Feed-in Tariff which could appreciably increase the savings that are shown on this EPC for solar photovoltaic panels, provided that both the product and the installer are certified by the Microgeneration Certification Scheme (or equivalent). Details of local MCS installers are available at www.microgenerationcertification.org.

Low and zero carbon energy sources

Low and zero carbon (LZC) energy sources are sources of energy that release either very little or no carbon dioxide into the atmosphere when they are used. Installing these sources may help reduce energy bills as well as cutting carbon.

LZC energy sources present: There are none provided for this home

Your home's heat demand

You could receive Renewable Heat Incentive (RHI) payments and help reduce carbon emissions by replacing your existing heating system with one that generates renewable heat and, where appropriate, having your loft insulated and cavity walls filled. The estimated energy required for space and water heating will form the basis of the payments. For more information go to www.energysavingtrust.org.uk/scotland/rhi.

Heat demand	Existing dwelling	Impact of loft insulation	Impact of cavity wall insulation	Impact of solid wall insulation
Space heating (kWh per year)	17,253	N/A	(1,804)	N/A
Water heating (kWh per year)	2,121			

Addendum

About this document

This Recommendations Report and the accompanying Energy Performance Certificate are valid for a maximum of ten years. These documents cease to be valid where superseded by a more recent assessment of the same building carried out by a member of an Approved Organisation.

The Energy Performance Certificate and this Recommendations Report for this building were produced following an energy assessment undertaken by an assessor accredited by Elmhurst (www.elmhurstenergy.co.uk), an Approved Organisation Appointed by Scottish Ministers. The certificate has been produced under the Energy Performance of Buildings (Scotland) Regulations 2008 from data lodged to the Scottish EPC register. You can verify the validity of this document by visiting www.scottishepcregister.org.uk and entering the report reference number (RRN) printed at the top of this page.

Assessor's name:

Assessor membership number:

Company name/trading name:

Address:

Mr. George Robb
EES/016118
J & E Shepherd
13 Albert Square

13 Albert Square Dundee

DD1 1XA
Phone number: 01382 200454

Email address: dundee@shepherd.co.uk

Related party disclosure: No related party

If you have any concerns regarding the content of this report or the service provided by your assessor you should in the first instance raise these matters with your assessor and with the Approved Organisation to which they belong. All Approved Organisations are required to publish their complaints and disciplinary procedures and details can be found online at the web address given above.

Use of this energy performance information

Once lodged by your EPC assessor, this Energy Performance Certificate and Recommendations Report are available to view online at www.scottishepcregister.org.uk, with the facility to search for any single record by entering the property address. This gives everyone access to any current, valid EPC except where a property has a Green Deal Plan, in which case the report reference number (RRN) must first be provided. The energy performance data in these documents, together with other building information gathered during the assessment is held on the Scottish EPC Register and is available to authorised recipients, including organisations delivering energy efficiency and carbon reduction initiatives on behalf of the Scottish and UK governments. A range of data from all assessments undertaken in Scotland is also published periodically by the Scottish Government. Further information on these matters and on Energy Performance Certificates in general, can be found at www.gov.scot/epc.

Advice and support to improve this property

There is support available, which could help you carry out some of the improvements recommended for this property on page 3 and stop wasting energy and money. For more information, visit greeners cotland.org or contact Home Energy Scotland on 0808 808 2282.

Home Energy Scotland's independent and expert advisors can offer free and impartial advice on all aspects of energy efficiency, renewable energy and more.

HOMEENERGYSCOTLAND.ORG
0808 808 2282
FUNDED BY THE SCOTTISH GOVERNMENT



survey report on:

Property address	62 Kingsway Dundee DD4 9BP	
Customer	Mr & Mrs John Penman	
Customer address	Whitehall House 33 Yeaman Shore Dundee DD1 4BJ	
Prepared by	J & E Shepherd	
Date of inspection	19th March 2020	



PART 1 - GENERAL

1.1 THE SURVEYORS

The Seller has engaged the Surveyors to provide the Single Survey Report and a generic Mortgage Valuation Report for Lending Purposes. The Seller has also engaged the Surveyors to provide an Energy Report in the format prescribed by the accredited Energy Company.

The Surveyors are authorised to provide a transcript or retype of the generic Mortgage Valuation Report on to Lender specific pro-forma. Transcript reports are commonly requested by Brokers and Lenders. The transcript report will be in the format required by the Lender but will contain the same information, inspection date and valuation figure as the generic Mortgage Valuation Report and the Single Survey. The Surveyors will decline any transcript request which requires the provision of information additional to the information in the Report and the generic Mortgage Valuation Report until the Seller has conditionally accepted an offer to purchase made in writing.

Once the Seller has conditionally accepted an offer to purchase made in writing, the Purchaser's lender or conveyancer may request that the Surveyors provide general comment on standard appropriate supplementary documentation. In the event of a significant amount of documentation being provided to the Surveyors, an additional fee may be incurred by the Purchaser. Any additional fee will be agreed in writing.

If information is provided to the Surveyors during the conveyancing process which materially affects the valuation stated in the Report and generic Mortgage Valuation Report, the Surveyors reserve the right to reconsider the valuation. Where the Surveyors require to amend the valuation in consequence of such information, they will issue an amended Report and generic Mortgage Valuation Report to the Seller. It is the responsibility of the Seller to ensure that the amended Report and generic Mortgage Valuation Report are transmitted to every prospective Purchaser.

The individual Surveyor will be a member of the Royal Institution of Chartered Surveyors who is competent to survey, value and report upon Residential Property¹.

If the Surveyors have had a previous business relationship within the past two years with the Seller or Sellers Agent or relative to the property, they will be obliged to indicate this by ticking the adjacent box.



The Surveyors have a written complaints handling procedure. This is available from the offices of the Surveyors at the address stated.

1.2 THE REPORT

The Surveyors will not provide an amended Report on the Property, except to correct factual inaccuracies.

The Report will identify the nature and source of information relied upon in its preparation.

The Surveyor shall provide a Market Value of the Property, unless the condition of the Property is such that it would be inappropriate to do so. A final decision on whether a loan will be granted rests with the Lender who may impose retentions in line with their lending criteria. The date of condition and value of the property will be the date of inspection.

To date, Purchasers have normally obtained their own report from their chosen Surveyor. By contrast, a Single Survey is instructed by the Seller and made available to all potential Purchasers in the expectation that the successful Purchaser will have relied upon it. The Royal Institution of Chartered Surveyors rules require disclosure of any potential conflict of interest when acting for the Seller and the Purchaser in the same transaction. The Single Survey may give rise to a conflict of interest and if this is of concern to any party they are advised to seek their own independent advice.

¹ Which shall be in accordance with the current RICS Valuation Standards (The Red Book) and RICS Rules of Conduct.

The Report and any expressions or assessments in it are not intended as advice to the Seller or Purchaser or any other person in relation to an asking price or any other sales or marketing decisions. The Report is based solely on the Property and is not to be relied upon in any manner whatsoever when considering the valuation or condition of any other property.

If certain minor matters are mentioned in the Report it should not be assumed that the Property is free of other minor defects.

Neither the whole nor any part of the Report may be published in any way, reproduced or distributed by any party other than the Seller, prospective purchasers and the Purchaser and their respective professional advisers without the prior written consent of the Surveyors.

1.3 LIABILITY

The Report is prepared with the skill and care reasonably to be expected of a competent residential surveyor who is a member of the Royal Institution of Chartered Surveyors.

The Report is addressed to the Seller and was prepared in the expectation that it (or a complete copy) along with these Terms and Conditions (or a complete copy) would (or, as the case might be, would have been) be disclosed and delivered to:-

- the Seller;
- any person(s) noting an interest in purchasing the Property from the Seller;
- any person(s) who make(s) (or on whose behalf is made) an offer to purchase the Property, whether or not that offer is accepted by the Seller;
- the Purchaser; and
- the professional advisers of any of these.

The Surveyors acknowledge that their duty of skill and care in relation to the Report is owed to the Seller and to the Purchaser. The Surveyors accept no responsibility or liability whatsoever in relation to the Report to persons other than the Seller and the Purchaser. The Seller and Purchaser should be aware that if a Lender seeks to rely on this Report they do so at their own risk. In particular, the Surveyors accept no responsibility or liability whatsoever to any Lender in relation to the Report. Any such Lender relies upon the Report entirely at their own risk.

1.4 GENERIC MORTGAGE VALUATION REPORT

The Surveyors undertake to the Seller that they will prepare a generic Mortgage Valuation Report, which will be issued along with the Single Survey. It is the responsibility of the Seller to ensure that the generic Mortgage Valuation Report is provided to every potential Purchaser.

1.5 TRANSCRIPT MORTGAGE VALUATION FOR LENDING PURPOSES

The Surveyors undertake that on being asked to do so by a prospective purchaser, or his/her professional advisor or Lender, they will prepare a Transcript Mortgage Valuation Report for Lending Purposes on terms and conditions to be agreed between the Surveyors and Lender and solely for the use of the Lender and upon which the Lender may rely. The decision as to whether finance will be provided is entirely a matter for the Lender. The Transcript Mortgage Valuation Report ² will be from information contained in the Report and the generic Mortgage Valuation Report.

² Which shall be in accordance with the current RICS Valuation Standards (The Red Book) and RICS Rules of Conduct

1.6 INTELLECTUAL PROPERTY

All intellectual property rights whatsoever (including copyright) in and to the Report, excluding the headings and rubrics, are the exclusive property of the Surveyors and shall remain their exclusive property unless they assign the same to any other party in writing.

1.7 PAYMENT

The Surveyors are entitled to refrain from delivering the Report to anyone until the fee and other charges for it notified to the Seller have been paid. Additional fees will be charged for subsequent inspections and Reports.

1.8 CANCELLATION

The Seller will be entitled to cancel the inspection by notifying the Surveyor's office at any time before the day of the inspection.

The Surveyor will be entitled not to proceed with the inspection (and will so report promptly to the Seller) if after arriving at the property, the Surveyor concludes that it is of a type of construction of which the surveyor has insufficient specialist knowledge to be able to provide the inspection satisfactorily. The Surveyor will also be entitled not to proceed if after arriving at the property, the surveyor concludes that the property is exempt under Part 3 of The Housing (Scotland) Act 2006 as detailed in the (Prescribed Documents) Regulations 2008. If there is a potential threat to their health or personal safety, the inspection may be postponed or cancelled, at the Surveyor's discretion.

In the case of cancellation or the inspection not proceeding, the Surveyor will refund any fees paid by the Seller for the inspection and Report, except for expenses reasonably incurred and any fee due in light of the final paragraph of this section.

In the case of cancellation by the Seller, for whatever reason, after the inspection has taken place but before a written report is issued, the Surveyor will be entitled to raise an Invoice equivalent to 80% of the agreed fee.

1.9 PRECEDENCE

If there is any incompatibility between these Terms and Conditions and the Report, these Terms and Conditions take precedence.

1.10 DEFINITIONS

- the "Lender" is the party who has provided or intends or proposes to provide financial assistance to the Purchaser towards the purchase of the Property and in whose favour a standard security will be granted over the Property;
- the "Transcript Mortgage Valuation Report for Lending Purposes" means a separate report, prepared by the Surveyor, prepared from information in the Report and the generic Mortgage Valuation Report, but in a style and format required by the Lender. The Transcript Mortgage Valuation Report for Lending Purposes will be prepared with the skill and care reasonably to be expected from a surveyor who is a member of the Royal Institution of Chartered Surveyors and who is competent to survey, value and report on the Property;
- the "Generic Mortgage Valuation Report" means a separate report, prepared by the Surveyor from information in the Report but in the Surveyor's own format;

- the "Market Value" is the estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion;
- the "Property" is the property which forms the subject of the Report;
- the "Purchaser" is the person (or persons) who enters into a contract to buy the Property from the Seller:
- a "prospective Purchaser" is anyone considering buying the Property;
- the "Report" is the report, of the kind described in Part 2 of these Terms and Conditions and in the form set out in part 1 of Schedule 1 of the Housing (Scotland) Act 2006 (Prescribed Documents) Regulations 2008;
- the "Seller" is/are the proprietor(s) of the Property;
- the "Surveyor" is the author of the Report on the Property; and
- the "Surveyors" are the firm or company of which the Surveyor is an employee, director, member or partner (unless the Surveyor is not an employee, director, member or partner, when the "Surveyors" means the Surveyor) whose details are set out at the head of the Report.
- the "Energy Report" is the advice given by the accredited Energy Company, based on information collected by the Surveyor during the Inspection, and also includes an Energy Performance Certificate, in a Government approved format.

PART 2 - DESCRIPTION OF THE REPORT

2.1 THE SERVICE

The Single Survey is a Report by an independent Surveyor, prepared in an objective way regarding the condition and value of the Property on the day of the inspection, and who is a member of the Royal Institution of Chartered Surveyors. It includes an Energy Report as required by Statute and this is in the format of the accredited Energy Company. In addition, the Surveyor has agreed to supply a generic Mortgage Valuation Report.

2.2 THE INSPECTION

The Inspection is a general surface examination of those parts of the Property which are accessible: in other words, visible and readily available for examination from ground and floor levels, without risk of causing damage to the Property or injury to the Surveyor.

All references to visual inspection refer to an inspection from within the property at floor level and from ground level within the site and adjoining public areas, without the need to move any obstructions. Any references to left or right are taken facing the front of the property.

The Inspection is carried out with the Seller's permission, without causing damage to the building or contents. Furniture, stored items and insulation are not moved.

Unless identified in the report the Surveyor will assume that no harmful or hazardous materials have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

The Surveyor will not carry out an asbestos inspection, and will not be acting as an asbestos inspector in completing a Single Survey of properties that may fall within the Control of Asbestos in the Workplace Regulations. In the case of flats it will be assumed that there is a duty holder, as defined in the Regulations and that a Register of Asbestos and effective Management Plan is in place, which does not require any expenditure, or pose a significant risk to health. No enquiry of the duty holder will be made.

2.3 THE REPORT

The Report will be prepared by the Surveyor who carried out the property inspection and will describe various aspects of the property as defined by the headings of the Single Survey report with the comments being general and unbiased. The report on the location, style and condition of the property, will be concise and will be restricted to matters that could have a material effect upon value and will omit items that, in the Surveyor's opinion, are not significant. If certain minor matters are mentioned, it should not be interpreted that the property is free of any other minor defects.

Throughout the report, the following repair categories will be used to give an overall opinion of the state of repair and condition of the property.

- Category 3: Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.
- 2. Category 2: Repairs or replacement requiring future attention, but estimates are still advised.
- 3. Category 1: No immediate action or repair is needed.

WARNING:

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions when the effect can be considerable.

Parts of the property, which cannot be seen or accessed, will not be reported upon and this will be stated. If the Surveyor suspects that a defect may exist within an unexposed area and which could have a material effect upon the value, he may recommend further investigation by specialist contractors.

2.4 SERVICES

Surveyors are not equipped or qualified to test the services and therefore no comment can be interpreted as implying that the design, installation and function of the services are in accordance/compliance with regulations, safety and efficiency expectations. However, comment is made where there is cause to suspect significant defects or shortcomings with the installations. No tests are made of any services or appliances.

2.5 ACCESSIBILITY

A section is included to help identify the basic information interested parties need to know to decide whether to view a property.

2.6 ENERGY REPORT

A section is included that makes provision for an Energy Report, relative to the property. The Surveyor will collect physical data from the property and provide such data in a format required by an accredited Energy Company. The Surveyor cannot of course accept liability for any advice given by the Energy Company.

2.7 VALUATION AND CONVEYANCER ISSUES

The last section of the Report contains matters considered relevant to the Conveyancer (Solicitor). It also contains the Surveyor's opinion both of the market value of the property and of the re-instatement cost, as defined below.

"Market Value" is the estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion. In arriving at the opinion of the Market Value, the Surveyor also makes various standard assumptions covering, for example, vacant possession; tenure and other legal considerations; contamination and hazardous materials; the condition of un-inspected parts; the right to use mains services; and the exclusion of curtains, carpets etc. from the valuation. In the case of flats, the following further assumptions are made that:

- There are rights of access and exit over all communal roadways, corridors, stairways etc. and to use communal grounds, parking areas, and other facilities;
- There are no particularly troublesome or unusual legal restrictions;
- There is no current dispute between the occupiers of the flats or any outstanding claims or losses; and the costs of repairs to the building are shared among the co-proprietors on an equitable basis.

Any additional assumption, or any found not to apply, is reported.

"Re-instatement cost" is an estimate for insurance purposes of the current cost of rebuilding the Property in its present form unless otherwise stated. This includes the cost of rebuilding the garage and permanent outbuildings, site clearance and professional fees, but excludes VAT (except on the fees).

Sellers or prospective Purchasers may consider it prudent to instruct a reinspection and revaluation after a period of 12 weeks (or sooner if appropriate) to reflect changing circumstances in the market and/or in the physical condition of the Property.

1. Information and scope of inspection

This section tells you about the type, accommodation, neighbourhood, age and construction of the property. It also tells you about the extent of the inspection and highlights anything that the surveyor could not inspect.

All references to visual inspection refer to an inspection from within the property without moving any obstructions and externally from ground level within the site and adjoining public areas. Any references to left or right in a description of the exterior of the property refer to the view of someone standing facing that part of the property from the outside.

The inspection is carried out without causing damage to the building or its contents and without endangering the occupiers or the surveyor. Heavy furniture, stored items and insulation are not moved. Unless identified in the report the surveyor will assume that no harmful or hazardous materials or techniques have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

Services such as TV/cable connection, internet connection, swimming pools and other leisure facilities etc. will not be inspected or reported on.

Description	The subjects comprise a detached bungalow with attic conversion.
A commodation	CROUND ELCOP. Enterno Vestibulo en d'Unil Livin a Rosa
Accommodation	GROUND FLOOR: Entrance Vestibule and Hall, Living Room, Dining Room, Kitchen, two Bedrooms and Shower Room with W.C.
	ATTIC FLOOR: Bedroom with en-suite Bathroom.
	ATTIC FLOOR, Bedroom with en-suite Bathroom.
Gross internal floor area (m²)	120 square metres, or thereby.
Gress internal floor area (iii)	120 Square metres, or thereby.
Not only a supplier of an all a sections	The subjects are situated fronting the Kingson successful and
Neighbourhood and location	The subjects are situated fronting the Kingsway outer ring road within a locality where surrounding properties are similar in
	character and design and the subjects are convenient to most local
	amenities.
Age	1930 approximately.
Age	1930 approximately.
Westler	D
Weather	Dry and sunny.
Chimney stacks	Visually inspected with the aid of binoculars where appropriate.
	The chimney is of brick construction roughcast externally and with a
	lead flashings adjacent.
Roofing including roof space	Sloping roofs were visually inspected with the aid of binoculars where appropriate.
	Flat roofs were visually inspected from ventors maints within
1	Flat roots were visually inspected from vantage points within
	Flat roofs were visually inspected from vantage points within the property and where safe and reasonable to do so from a 3m ladder externally.
	the property and where safe and reasonable to do so from a 3m ladder externally.
	the property and where safe and reasonable to do so from a


	If this is not possible, then physical access to the roof space may be taken by other means if the Surveyor deems it safe and reasonable to do so.
	The roof over is pitched and overlaid in slates with tiled ridge and slated hip caps. There is also a flat felt clad roof over the rear bay projection.
	Limited access was afforded to the eaves area and where seen had storage items therein and was also insulated.
	The main roof void area has been converted into living accommodation at sometime in the past.
Rainwater fittings	Visually inspected with the aid of binoculars where appropriate.
	Rainwater goods are a mixture of cast-iron and PVC.
Main walls	Visually inspected with the aid of binoculars where appropriate.
	Foundations and concealed parts were not exposed or inspected.
	The main walls appear to be 300mm cavity brick construction roughcast externally.
Windows, external doors and joinery	Internal and external doors were opened and closed where keys were available.
	Random windows were opened and closed where possible.
	Doors and windows were not forced open.
	Windows are of the uPVC style which are double glazed with the main entrance door being of a composite style.
	There are uPVC double glazed French doors to the rear of the dining room and a uPVC double glazed rear entrance door.
	There are timber casement Velux windows at attic level.
External decorations	Visually inspected.
	Vinyl finish to most windows and doors with painted/wood stained external joinery timbers.
Conservatories / porches	None.

Communal areas	None.
Garages and permanent outbuildings	Visually inspected. Situated within the garden area is a garage/work store which is of concrete sectional construction with a shallow pitched roof over clad in felt sheeting. The garage was full of storage items at the time of inspection and there is a fibreglass up and over entrance
Outside areas and boundaries	Visually inspected.
	The front garden area has a mono block access drive with an area laid to gravel and an area laid to grass. Boundaries are generally of concrete block walling.
	The rear garden area has been laid to grass with a paved patio area and boundary walls are of concrete blockwork. There are also areas of concrete block garden retaining walls.
Ceilings	Visually inspected from floor level. Strapped and lined in lath and plaster with areas lined in
Internal walls	Visually inspected from floor level.
	Using a moisture meter, walls were randomly tested for dampness where considered appropriate.
	Strapped and lined in lath and plaster with areas plastered on the hard and areas lined in plasterboard.
Floors including sub floors	Surfaces of exposed floors were visually inspected. No carpets or floor coverings were lifted.
	Flooring throughout is generally of suspended timber although there
	Flooring throughout is generally of suspended timber although there is an area of composite flooring within the front vestibule area. The property was fully floor covered at the time of inspection and no access was obtained to any sub-floor area.
Internal joinery and kitchen fittings	is an area of composite flooring within the front vestibule area. The property was fully floor covered at the time of inspection and no

Chimney breasts and fireplaces	Visually inspected.
	No testing of the flues or fittings was carried out.
	There is a gas flame fire situated within the living room set within a marble surround or similar. This fire was not in operation during the course of inspection.
Internal decorations	Visually inspected.
	Wallpaper/emulsion finish to walls and ceilings with walls in the en-suite bathroom being fully tiled and kitchen walls being part tiled. Walls within the shower room have been fully tiled with the ceiling being PVC lined.
Cellars	None.
Electricity	Accessible parts of the wiring were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on. Mains supply of electricity serving a 13 amp ring main with the
	consumer unit and electric meter within the vestibule cupboard.
Gas	Accessible parts of the system were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on.
	Mains supply of gas.
Water, plumbing, bathroom fittings	Visual inspection of the accessible pipework, water tanks, cylinders and fittings without removing any insulation.
	No tests whatsoever were carried out to the system or appliances.
	Mains supply of water with internal plumber work where seen being of copper and PVC and plumbing is provided for both a washing machine and dish washer. There is a three piece suite within both shower room and en-suite bathroom and the property benefits from an external water tap.
	There is a cold storage water tank within the roof void area and areas of lead plumber work although it is understood that these items are no longer in use.

Heating and hot water	Accessible parts of the system were visually inspected apart from communal systems, which were not inspected.
	No tests whatsoever were carried out to the system or appliances.
	The property has the benefit of a gas heating system serving steel panelled radiators which are served by means of the Worcester Greenstar combination central heating boiler. It is understood that this boiler also provides for hot water. There is a room thermostat within the hallway.
Drainaga	Drainage severe etc. were not lifted
Drainage	Drainage covers etc. were not lifted.
	Neither drains nor drainage systems were tested.
	Drainage is presumed to be connected to the main public sewer.
Fire, smoke and burglar alarms	Visually inspected.
	No tests whatsoever were carried out to the system or appliances.
	The property benefits from an alarm system and smoke detectors are fitted.
Ann additional limita to increation	
Any additional limits to inspection	Inspection of the roof void area was restricted due to storage and insulation materials and only a limited view was possible of part of the eaves area. The roof void area has been converted into living accommodation in the past.
	Windows were opened on a random basis only and the property was fully floor covered, furnished and occupied at the time of inspection with cupboards full of possessions.
	No access was afforded to any sib-floor area and no access obtained behind/under sanitary fittings.
	An inspection for Japanese Knotweed was not carried out. This is a plant which is subject to control regulation, is considered to be invasive and one which can render a property unsuitable for some mortgage lenders. It is therefore assumed that there is no Japanese Knotweed within the boundaries of the property or its neighbouring property. Identification of Japanese Knotweed is best undertaken by a specialist contractor.

Sectional Diagram showing elements of a typical house



Reference may be made in this report to some or all of the above component parts of the property. This diagram may assist you in locating and understanding these items.

- 1) Chimney pots
- 2) Coping stone
- 3) Chimney head
- 4) Flashing
- (5) Ridge ventilation
- 6) Ridge board
- 7) Slates / tiles
- (8) Valley guttering
- 9) Dormer projection
- 10 Dormer flashing
- 11) Dormer cheeks
- 12) Sarking
- 13) Roof felt
- (14) Trusses
- 15) Collar
- (16) Insulation
- 17) Parapet gutter
- 18) Eaves guttering
- 19) Rainwater downpipe
- O Verge boards /skews
- 21) Soffit boards
- 22) Partition wall
- 23) Lath / plaster
- 24) Chimney breast
- (25) Window pointing
- S
- 26) Window sills
- (27) Rendering
- 28) Brickwork / pointing
- 29) Bay window projection
- 30 Lintels
- (31) Cavity walls / wall ties
- 32) Subfloor ventilator
- 33) Damp proof course
- 34) Base course
- 35) Foundations
- 36) Solum
- 37) Floor joists
- 38) Floorboards
- 9) Water tank
- 40) Hot water tank

2. Condition

This section identifies problems and tells you about the urgency of any repairs by using one of the following three categories:

Category 3	Category 2	Category 1
	Repairs or replacement requiring future attention, but estimates are still advised.	

Structural movement		
Repair category	1	
Notes	There was no evidence of significant structural movement within the limitations of our inspection.	

Dampness, rot and infestation	
Repair category	1
Notes	Damp meter readings were taken where considered appropriate within the property and moisture levels were found to be within an acceptable range.

Chimney stacks	
Repair category	2
Notes	There are areas of weathered roughcast to the chimney. Ongoing maintenance and repair should be anticipated to the chimney stack and flashings in accordance with good maintenance practice.

Roofing including roof space	
Repair category	2
Notes	There are a small number of slipped/cracked roofing slates and there is a flat felt clad roof over the rear bay projection. Flat roof claddings do have a limited life and ongoing maintenance and repair should be anticipated and budgeted for. Roofing contractors recommend that roof coverings are inspected regularly in order to ensure they remain water tight.

Rainwater fittings	
Repair category	1
Notes	Within the limitations of our inspection rainwater goods were seen to be free from significant defect. although it was dry during the course of inspection. The rainwater goods should be tested under a prolonged heavy downpour and any necessary remedial works implemented thereafter.

Main walls	
Repair category	1
Notes	Within the limitations of our inspection, no significant defects were noted, however normal levels of maintenance are recommended.

Windows, external doors and joinery	
Repair category	2
Notes	There are areas of weathered plaster to the front mullions of the front bay projections and there are one or two defective vacuum seals to some Velux windows. Ongoing maintenance and repairs should be anticipated.

External decorations	
Repair category	1
Notes	External decoration appeared in good condition.

Conservatories/porches	
Repair category	-
Notes	Not applicable.

Communal areas	
Repair category	-
Notes	Not applicable.

Garages and permanent outbuildings	
Repair category	2
Notes	It is understood that the flat roof cladding over the garage has recently been replaced. The garage is of a type which is prone to water penetration. A detailed inspection of the garage as not possible due to storage items. Slight cracking

Outside areas and boundaries	
Repair category	2
Notes	There are areas of weathered pointing to boundary walls and boundary walls should be checked on a regular basis and maintained as necessary.

Ceilings	
Repair category	1
Notes	Within the limitations of our inspection no significant defects were noted.

Internal walls	
Repair category	1
Notes	Within the limitations of our inspection no significant defects were noted.

Floors including sub-floors	
Repair category	1
Notes	Due to fitted carpets and floor coverings no detailed inspection of floors was possible and accordingly no comment can be made on their condition.

Internal joinery and kitchen fittings	
Repair category	1
Notes	It has been presumed that safety glass has been incorporated to the internal glazed doors.
	Within the limitations of our inspection no significant defects were noted.

Chimney breasts and fireplaces	
Repair category	1
Notes	It has been presumed that the gas fire has been properly serviced and maintained in accordance with current regulations and standards. All flue linings should be checked, repaired if necessary and swept prior to any fire being reused.

Internal decorations	
Repair category	1
Notes	Internal decoration was in good condition.

Cellars	
Repair category	-
Notes	Not applicable.

Electricity	
Repair category	1
Notes	The Institute of Engineering and Technology recommends that inspections and testings are undertaken at least every ten years and on a change of occupancy. It should be appreciated that only the most recently constructed or re-wired properties will have installations which fully comply with present IET regulations. There is an old fuse board within the meter cupboard although it is understood that this is no longer in use.

Gas	
Repair category	1
Notes	In the interests of safety and in light of recent regulations it would be prudent to have all gas appliances checked by a Gas Safe registered contractor.

Water, plumbing and bathroom fittings		
Repair category	1	
Notes	No tests have been undertaken of the system, however within the limitations of our inspection, no significant defects were noted.	
	We have presumed that sealants around the sanitary fittings are fully functional with no defects to the adjacent areas. A precautionary check is always advised below/under sanitary fittings are sealants are prone to leakage.	
	There was evidence of lead plumber work within the roof void area although it is understood that this lead plumber work is no longer in use.	

Heating and hot wa	ter
Repair category	1
Notes	It is understood that the central heating boiler is still under warranty and was installed in March 2019. It is presumed that the heating system has been

properly serviced and maintained in accordance with current regulations and standards.
standards.

Drainage	
Repair category	1
Notes	All foul and surface water drainage is assumed to be to the main public sewer. The system was not tested.

Set out below is a summary of the condition of the property which is provided for reference only. You should refer to the previous comments for detailed information.

Structural movement	1
Dampness, rot and infestation	1
Chimney stacks	2
Roofing including roof space	2
Rainwater fittings	1
Main walls	1
Windows, external doors and joinery	2
External decorations	1
Conservatories/porches	-
Communal areas	-
Garages and permanent outbuildings	2
Outside areas and boundaries	2
Ceilings	1
Internal walls	1
Floors including sub-floors	1
Internal joinery and kitchen fittings	1
Chimney breasts and fireplaces	1
Internal decorations	1
Cellars	-
Electricity	1
Gas	1
Water, plumbing and bathroom fittings	1
Heating and hot water	1
Drainage	1

Category 3

Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.

Category 2

Repairs or replacement requiring future attention, but estimates are still advised.

Category 1

No immediate action or repair is needed.

Remember

The cost of repairs may influence the amount someone is prepared to pay for the property. We recommend that relevant estimates and reports are obtained in your own name.

Warning

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions where the effect can be considerable.

3. Accessibility information

Guidance notes on accessibility information

Three steps or fewer to a main entrance door of the property:

In flatted developments the 'main entrance' would be the flat's own entrance door, not the external door to the communal stair. The 'three steps or fewer' are counted from external ground level to the flat's entrance door. Where a lift is present, the count is based on the number of steps climbed when using the lift.

Unrestricted parking within 25 metres:

For this purpose, 'Unrestricted parking' includes parking available by means of a parking permit. Restricted parking includes parking that is subject to parking restrictions, as indicated by the presence of solid yellow, red or white lines at the edge of the road or by a parking control sign, parking meters or other coin-operated machines.

1. Which floor(s) is the living accommodation on?	First floor and attic.
2. Are there three steps or fewer to a main entrance door of the property?	Yes X No
3. Is there a lift to the main entrance door of the property?	Yes No X
4. Are all door openings greater than 750mm?	Yes No X
5. Is there a toilet on the same level as the living room and kitchen?	Yes X No
6. Is there a toilet on the same level as a bedroom?	Yes X No
7. Are all rooms on the same level with no internal steps or stairs?	Yes No X
8. Is there unrestricted parking within 25 metres of an entrance door to the building?	Yes X No

4. Valuation and conveyancer issues

This section highlights information that should be checked with a solicitor or licensed conveyancer. It also gives an opinion of market value and an estimated reinstatement cost for insurance purposes.

Matters for a solicitor or licensed conveyancer

Where defects or repairs have been identified within this report it is recommended that, prior to entering into any legally binding sale or purchase contract, further specialist's or contractor's advice and estimates should be obtained, to establish the implications, if any, on a potential offer to purchase or the sale price likely to be achieved for the property.

The attic area was converted into living accommodation in or around 2000 although this has not been accurately confirmed. It should be confirmed that all relevant statutory documentation was obtained and is in order and all such documentation will require to be placed with Titles for safe keeping.

French doors have also been installed to the rear of the dining area and it is assumed that all relevant documentation relating to this is also in place and in order.

Estimated reinstatement cost for insurance purposes

For Reinstatement Cost Assessment purposes, it is recommended that the subjects be insured for a sum of not less than £280,000 (TWO HUNDRED AND EIGHTY THOUSAND POUNDS STERLING).

This figure is the estimate of the cost of rebuilding the premises and bears no direct relationship to current market value.

Valuation and market comments

Having considered matters, taking account of our general observations on site, we are of the opinion that the Market Value of the subjects in their present condition and with the benefit of vacant possession may be fairly stated in the sum of £265,000 (TWO HUNDRED AND SIXTY FIVE THOUSAND POUNDS STERLING).

The property forms suitable security for mortgage purposes subject to the specific lending criteria of any mortgage provider.

Security Print Code [454459 = 6439] Electronically signed
George B Robb
J & E Shepherd
13 Albert Square, Dundee, DD1 1XA
23rd March 2020



Property Address									
Address Seller's Name Date of Inspection	62 Kingsway, Dundee, DD4 9BP Mr & Mrs John Penman 19th March 2020								
Property Details									
Property Type	House X Bungalow Purpose built maisonette Converted maisonette Purpose built flat Converted flat Tenement flat Flat over non-residential use Other (specify in General Remarks)								
Property Style	X Detached Semi detached Mid terrace End terrace Back to back High rise block Low rise block Other (specify in General Remarks)								
Does the surveyor believe that the property was built for the public sector, e.g. local authority, military, police?									
Flats/Maisonettes only Approximate Year of 0	No. of units in block								
Tenure									
X Absolute Ownership	Leasehold Ground rent £ Unexpired years								
Accommodation									
Number of Rooms	2 Living room(s) 3 Bedroom(s) 1 Kitchen(s) 2 Bathroom(s) 2 WC(s) 0 Other (Specify in General remarks)								
	cluding garages and outbuildings) 120 m² (Internal) m² (External) greater than 40%) X Yes No								
Garage / Parking / 0	Outbuildings								
X Single garage Available on site?	□ Double garage □ Parking space □ No garage / garage space / parking space X Yes □ No								
Permanent outbuildings:									
None.									

Construction							
Walls	X Brick	Stone	Concrete	Timber frame	Other	r (specify in Gen	eral Remarks)
Roof	Tile	X Slate	Asphalt	Felt	Other	r (specify in Gen	eral Remarks)
Special Risks							
Has the property	suffered struc	tural moveme	ent?			Yes	X No
If Yes, is this rece	nt or progres	sive?				Yes	No
Is there evidence, history, or reason to anticipate subsidence, heave, landslip or flood in the immediate vicinity?							
If Yes to any of th	e above, prov	ride details in	General Remark	KS.			
Service Connec	ctions						
Based on visual ir of the supply in G			ices appear to be	e non-mains, pleas	se comment	on the type a	nd location
Drainage	X Mains	Private	None	Water	X Mains	Private	None
Electricity	X Mains	Private	None	Gas	X Mains	Private	None
Central Heating	X Yes	Partial	None				
Brief description of	of Central Hea	ıting:					
Gas fired radiato	or system.						
Site							
Apparent legal iss	sues to be ver	ified by the c	onveyancer. Ple	ase provide a brie	f description	in General R	emarks.
Rights of way		es / access		· amenities on separate	·	red service conn	
Ill-defined boundar	ries	Agricul	tural land included w	ith property	Othe	er (specify in Ge	neral Remarks)
Location							
X Residential suburb	Re	sidential within to	own / city Mix	ed residential / comme	rcial Mair	nly commercial	
Commuter village	Re	mote village	Isol	ated rural property	Othe	er (specify in Ge	neral Remarks)
Planning Issues	s						
Has the property been extended / converted / altered?							
ii 103 provide det		a Nomarks.					
Roads							
X Made up road	Unmade roa	d Partly	completed new road	Pedestrian a	ccess only	Adopted	Unadopted

General Remarks					
The property comprises a detached bungalow with attic conversion fronting the Kingsway outer ring road within a locality where surrounding properties are similar in character and design. The subjects are convenient to most local amenities.					
The attic has been converted into living accommodation in the past although the exact date is not known although thought to be around 2000. French doors have also been installed to the rear of the dining room. It has been presumed that any relevant statutory documentation has been obtained and is in order and any such documentation will require to be placed with Titles for safe keeping.					
The property appeared in a condition consistent with age and type of construction and during the course of inspection minor defects were noted which are not uncommon for a property of this type, age and character and which should be capable of remedy by routine maintenance and repair.					
Essential Repairs					
None					

Comment on Mortgagea	bility	
The property forms suitable mortgage provider.	le security for mortgage purposes subject to the specific lending criteria o	f any
Valuations		
Market value in present con Market value on completion Insurance reinstatement va (to include the cost of total it Is a reinspection necessary	£ 265,000 £ n/a £ 280,000	
Buy To Let Cases		
month Short Assured Tenai	ge of monthly rental income for the property assuming a letting on a 6 ncy basis? here there is a steady demand for rented accommodation of this type?	£ No
is the property in an area w	nere there is a steady demand for refited accommodation or this type?	∐ Yes ∐ No
Declaration		
Signed Surveyor's name	Security Print Code [454459 = 6439] Electronically signed by:- George B Robb	
Professional qualifications	MRICS	
Company name	J & E Shepherd	
Address	13 Albert Square, Dundee, DD1 1XA	
Telephone	01382 200454	
Fax	01382 878008	
Report date	23rd March 2020	